

General Environmental Incident Summary

Incident: 2070 **Date/Time Notice:** 10/15/2013 0955 **DEM Incident No:**

Responsible Party: Bridger Pipeline LLC

Date Incident: 10/15/2013 **Time Incident:** 0830 **Duration:**

County: Mountrail **Twp:** 151 **Rng:** 91 **Sec:** 1 **Qtr:** NW

Lat: 47.92715 **Long:** -102.26830 **Method:** Derived from TRS

Location Description: EOG Liberty 8-01 production battery.

Submitted By: Bob Dundas

Affiliation:

Address:

307-247-3702 ©

City:

State:

Zip:

Received By:

Contact Person: Bob Dundas
P.O. Drawer 2360
Casper, WY 82602

Distance Nearest Occupied Building:

Type of Incident: Pump Leak

Description of Released Contaminant: crude oil

Volume Spilled: 15.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: No

Cause of Incident:

The seal in the gear pump failed. Approximately 15 barrels of crude oil was released. All oil is fully contained within the pump secondary containment.

Risk Evaluation:

The release poses no risks to the environment or the public.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

A small area of soil in the dike has been impacted by the release. As the spill is fully contained within the dike, no offsite impacts occurred.

Action Taken or Planned:

Free product will be collected with a vacuum truck. Absorbent material will be used to absorb residual oil. If necessary, impacted soils will be excavated and disposed appropriately.

Wastes Disposal Location: To be determined.

Agencies Involved:

Updates

Date: 10/15/2013 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Pump failure release into secondary containment, according to the report. Forward to O&G as it occurred on an E&P location.